




White Wolf Looking North, October 24, 1933



White Wolf Duplex Cabin 1/2, October 24, 1933



Main Lodge Looking West, September 2010



Main Lodge Looking North, September 2010





Main Lodge Looking South, September 2010



Duplex Cabins 1/2, Looking Southwest





Duplex Cabin 1/2, Looking Northwest



White Wolf Storage Building, Looking Southeast





Dirt Path to Cabins



Dirt Path to Parking Lot



Trees Crowding Foundation and Roofline of the Porch



Inaccessible Area Adjacent to Chimney



Deterioration of Horizontal Siding, North Shed



Deterioration of Horizontal Siding, North Shed







Inadequate Roofing at Chimney



Detached Battens above Storage Space



Chimney with Buttress



Chimney Looking East up Buttress





Deterioration of Porch Column



Leaning and Displace Porch Column



Footing, Shims, and Broken Floor Joists



Deteriorated Sill Plate and Column



Deterioration of Sill Plate & Wall Studs at North Side of Kitchen



Separation of Structure at North Gable



Typical Blocking at Piers



Typical Rotation of at Columns at Piers