


Installation of Storm Windows on Superintendent's House (Quarters #2)
Photos



Superintendent's House - front (north) facade



Superintendent's House - rear (south) facade



Exterior view of window at James Madison's Montpelier. The window has an interior storm window. FRSP proposes to use similar storm windows.



Interior view of window at James Madison's Montpelier. The window has an interior storm window. FRSP proposes to use similar storm windows.



Interior view of window at James Madison's Montpelier. The window has an interior storm window. Detail of magnetic attachment. FRSP proposes to use similar storm windows.



Interior view of window at James Madison's Montpelier. The window has an interior storm window. Detail of magnetic attachment. FRSP proposes to use similar storm windows.



Typical double hung sash window in the Superintendent's House.
FRSP proposes to install an interior storm window.



Detail of frame for typical double hung sash window in the Superintendent's House.
FRSP proposes to install an interior storm window.



Typical casement window in the Superintendent's House.
FRSP proposes to install an interior storm window.