NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Partial West Elevation
Date: 6/20/07
Photo: 19 of 73

013 NNNN 003 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 101 – Door D101
Date: 6/20/07
Photo: 20 of 73

013 NNNN 004 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 101- Door D101 – Transom
Detail
Date: 6/20/07
Photo: 21 of 73

018 NNNN 005 07.06.07 NEG#---

22 of 73 Room 102 - Stair
23 of 73 Room 102 - Door D102
24 of 73 Room 102 - View to West

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 102 - Stair
Date: 6/20/07
Photo: 22 of 73

018 NNNN 009 07.06.07 NEG# ---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 102 – Door D102
Date: 6/20/07
Photo: 23 of 73

018 NNNN 007 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 102 – View to West
Date: 6/20/07
Photo: 24 of 73

018 NNNN 008 07.06.07 NEG#---



25 of 73 Room 103 - West Elevation Including Stair Railing
26 of 73 First Floor Stair Newel Post Detail
27 of 73 Room 103 - View West with Ceiling Damage and D109

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 103 – View West with Ceiling Damage and D109
Date: 6/20/07
Photo: 27 of 73

018 NNNN 016 07.06.07 NEG# ---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 103 – West Elevation Including Stair Railing
Date: 6/20/07
Photo: 25 of 73

018 NNNN 015 07.06.07 NEG# ---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: First Floor Stair Newel Post Detail
Date: 6/20/07
Photo: 26 of 73

018 NNNN 010 07.06.07 NEG# ---

28 of 73 Room 103 - Partial South Elevation with Door D103A
29 of 73 Room 104 - East Elevation
30 of 73 Room 104 - South Elevation

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 103 – Partial South Elevation with Door D103A
Date: 6/20/07
Photo: 28 of 73

018 NNNN 017 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 104 – East Elevation
Date: 6/20/07
Photo: 29 of 73

018 NNNN 003 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 104 – South Elevation
Date: 6/20/07
Photo: 30 of 73

018 NNNN 001 07.06.07 NEG#---

31 of 73 Room 104 - Fireplace Detail - South Elevation
32 of 73 Room 104 - Fireplace - South Elevation
33 of 73 Room 105 - Ceiling Damage

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 104 – Fireplace Detail – South Elevation
Date: 6/20/07
Photo: 31 of 73

018 NNNN 006 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 104 –Fireplace – South Elevation
Date: 6/20/07
Photo: 32 of 73

018 NNNN 002 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 105 – Ceiling Damage
Date: 6/20/07
Photo: 33 of 73

018 NNNN 013 07.06.07 NEG#---

34 of 73 Room 105 - Fireplace Detail
35 of 73 Room 105 - Fireplace Detail -South Elevation
36 of 73 Room 105 - West and Partial South Elevation

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 105 – Fireplace Detail
Date: 6/20/07
Photo: 34 of 73

018 NNNN 014 07.06.07 NEG# ---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 105 – Fireplace Detail –
South Elevation
Date: 6/20/07
Photo: 35 of 73

018 NNNN 011 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 105 – West and Partial South
Elevation
Date: 6/20/07
Photo: 36 of 73

018 NNNN 012 07.06.07 NEG#



37 of 73 Room 108 - North Elevation
38 of 73 Room 108 - West Elevation - Wall Damage
39 of 73 Room 109- West Elevation with D110

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 108 – North Elevation
Date: 6/20/07
Photo: 37 of 73

018 NNNN 018 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 108 – West Elevation - Wall Damage
Date: 6/20/07
Photo: 38 of 73

018 NNNN 019 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 109 – West Elevation with D110
Date: 6/20/07
Photo: 39 of 73

018 NNNN 021 07.06.07 NEG#---

40 of 73 Room 109 - Window W105 - South Elevation
41 of 73 Room 109 - Change in Floor Material
42 of 73 Room 109 - South Elevation - Windows W104 and W105

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 109 – Window W105 – South Elevation
Date: 6/20/07
Photo: 40 of 73

045 1NN1 001 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 109 – Change in Floor Material
Date: 6/20/07
Photo: 41 of 73

045 1NN1 006 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 109 – South Elevation – Windows W104 and W105
Date: 6/20/07
Photo: 42 of 73

018 1NN1 020 07.06.07 NEG#---



43 of 73 Room 110 - Door D110A - South Elevation
44 of 73 Room 110 -Hearth Detail at Fireplace
45 of 73 Room 110 - South Elevation

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 110 – Door D110A – South Elevation
Date: 6/20/07
Photo: 43 of 73

045 1NN1 003 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 110 – Hearth Detail at Fireplace
Date: 6/20/07
Photo: 44 of 73

045 1NN1 005 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 110 – South Elevation
Date: 6/20/07
Photo: 45 of 73

045 1NN1 002 07.06.07 NEG#---

46 of 73 Room 110 - Fireplace - East Elevation
47 of 73 Room 201 - South Elevation with W205
48 of 73 Room 201 - View of Stair Down to First Floor

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 110 – Fireplace – East Elevation
Date: 6/20/07
Photo: 46 of 73

045 1NN1 004 07.06.07 NEG#----

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 201 –South Elevation with W205
Date: 6/20/07
Photo: 47 of 73

5.07 NEG#----

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 201 – View of Stair Down to First Floor
Date: 6/20/07
Photo: 48 of 73

.07 NE

49 of 73 Room 201 - Newel Post Detail of Stair to Third Floor
50 of 73 Room 202 - Detail of Stair to Third Floor
51 of 73 Room 202 - Tread Detail of Stair to Third Floor

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 201 – Newel Post Detail of Stair to Third Floor
Date: 6/20/07
Photo: 49 of 73

018 NNNN 034 07.06.07 NEG# —

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 202 – Detail of Stair to Third Floor
Date: 6/20/07
Photo: 50 of 73

018 NNNN 034 07.06.07 NEG# —

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 202 – Tread Detail of Stair to Third Floor
Date: 6/20/07
Photo: 51 of 73

018 NNNN 035 07.06.07 NEG# —



52 of 73 Room 202 - Tread and Baluster Detail
53 of 73 Room 202 - Underside of Stair to Third Floor
54 of 73 Room 203 - West Elevation with Doors D203A-B

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 202 – Tread and Baluster Detail
Date: 6/20/07
Photo: 52 of 73

018 NNNN 035 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 202 – Underside of Stair to Third Floor
Date: 6/20/07
Photo: 53 of 73

018 NNNN 033 07.06.07 NEG#---

018 NNNN 029 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 203 – West Elevation with Doors D203A-B
Date: 6/20/07
Photo: 54 of 73

55 of 73 Room 203 - Door D204 - South Elevation
56 of 73 Room 203- Partial South and East Elevation with W201
57 of 73 Room 203 - East Elevation - W201-03

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 203 – Door D204 – South Elevation
Date: 6/20/07
Photo: 55 of 73

018 NNNN 032 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 203 – Partial South and East Elevation with W201
Date: 6/20/07
Photo: 56 of 73

018 NNNN 031 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 203 – East Elevation – W201-03
Date: 6/20/07
Photo: 57 of 73

018 NNNN 028 07.06.07 NEG#---



58 of 73 Room 203 -Ceiling
59 of 73 Room 205 - D206
60 of 73 Room 205 - West Elevation with W204

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 203 - Ceiling
Date: 6/20/07
Photo: 58 of 73

018 NNNN 030 07.06.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 205 – D206
Date: 6/20/07
Photo: 59 of 73

.07 NEG#---

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 205 – West Elevation with W204
Date: 6/20/07
Photo: 60 of 73

61 of 73 Room 207 - South Elevation
62 of 73 Room 208 - East Elevation with D208A
63 of 73 Room 208 - South and Partial West Elevation

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 207 – South Elevation
Date: 6/20/07
Photo: 61 of 73

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 208 – East Elevation with D208A
Date: 6/20/07
Photo: 62 of 73

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 208 – South and Partial West Elevation
Date: 6/20/07
Photo: 63 of 73

64 of 73 Room 209 - Plaster Damage
65 of 73 Room 210 - West Elevation with W210
66 of 73 Room 210 - South Elevation with W209

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

.07 NEG#——

Description: Room 209 – Plaster Damage
Date: 6/20/07
Photo: 64 of 73

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

.07 NEG#——

Description: Room 210 – West Elevation with W210
Date: 6/20/07
Photo: 65 of 73

NEG#——

.07

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 210 – South Elevation with W209
Date: 6/20/07
Photo: 66 of 73

67 of 73 Room 301 - View to West with W305
68 of 73 Room 302 - East and Partial North Elevation with W301
69 of 73 Room 303 - East Elevation with Windows W302-3

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

07 NEG#

Description: Room 301- View to West with W305
Date: 6/20/07
Photo: 67 of 73

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

07 NEG#

Description: Room 302 – East and Partial North Elevation with W301
Date: 6/20/07
Photo: 68 of 73

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

07 NEG#

Description: Room 303 – East Elevation with Windows W 302-3
Date: 6/20/07
Photo: 69 of 73



70 of 73 Room 303 - Door 304 - South Elevation
71 of 73 Room 305 - Door D305 - North Elevation
72 of 73 Room 305- West Elevation with W304

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: - Room 303 – Door 304
–South Elevation
Date: 6/20/07
Photo: 70 of 73

.07 NEG# ----

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 305 – Door D305 – North Elevation
Date: 6/20/07
Photo: 71 of 73

.07 NEG# ----

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 305 – West Elevation with W304
Date: 6/20/07
Photo: 72 of 73



73 of 73 Room 305 - Door D306 -South Elevation

NPS Task Order Abbrev.- CAWO
NPS PMIS Ref#- 125623
Carter G. Woodson Home National Historic Site
1538 Ninth St, NW
Washington, DC 20009
NPS-NCP-E

Description: Room 305 – Door D306 –South Elevation
Date: 6/20/07
Photo: 73 of 73

6.07 NEG#----