

Installation of Handrails on Entrances to Chatham Manor
Photos



East façade of Chatham Manor



East entrance to Chatham Manor and elliptical steps.



East entrance to Chatham Manor. Black lines to the left of the door represent proposed railing attached to the exterior wall.



Close up of east entrance to Chatham Manor. Black lines to the left of the door represent proposed railing attached to the exterior wall.



West entrance to Chatham Manor and elliptical steps.



West entrance to Chatham Manor. Black lines to the right of the door represent proposed railing attached to the exterior wall.



Close up of west entrance to Chatham Manor. Black lines to the left of the door represent proposed railing attached to the exterior wall.



Example of a handrail similar to what is being proposed.



Existing railings on a west entrance to Chatham Manor. These railings date from the mid-20th century. This entrance is not open to the public, as it accesses park office space.



The removable slip-over steps in use at the Gari Melchers Home and Studio Belmont. This alternative would create additional safety concerns at Chatham Manor, plus it is not compatible with the elliptical steps at Chatham.