
Replace Doors and Install Air Conditioning to the Chatham Public Restrooms Photos



Chatham Carriage House and Stable – converted to public restrooms in 1981



Door for public Men's Restroom – will be replaced with a metal door




Visible damage to the door frame of the public Men's Restroom



Visible damage to the bottom of the door for the public Men's Restroom – will be replaced with a metal door



Interior wall of the public Men's Restroom – head/fan coil until will be mounted on the wall



Interior wall of the public Women's Restroom – head/fan coil until will be mounted on the wall



Interior of the "boathouse" section of the Carriage House and Stable – currently used for storage, the space will be cleared and the two compressor units will be installed in this area



Exterior view of the "boathouse" section of the Carriage House and Stable – the compressor units will be hidden from view inside the structure




The openings of the "boathouse" section of the Carriage House and Stables are covered with slats, which will allow for air circulation – the compressor units will be hidden from view inside the structure



Example of the wall mounted HVAC head/fan coil unit



Example of the compressor unit



The two red lines to the left show locations for the wall-mounted head/coil units. The location for the compressors is indicated by the red line to the right.