

Upgrade HVAC System in Chatham Buildings
Photos



Chatham Manor



One of seven chiller units in the attic of Chatham Manor. The units will be removed



Looking from a second floor office in Chatham Manor into the bathroom that will house the new air handler



Inside the former bathroom on the second floor of Chatham Manor. The bathtub is visible below the makeshift cabinets holding office equipment. A wood support will be built over the bathtub and the air handler will be placed on the platform. The ductwork will vent through a hole cut in the plywood ceiling above.



Chatham Carriage House



Heat pump behind the Chatham Carriage House, that serves the office and library in the building.
The heat pump will be replaced.



Air handler inside the Chatham Carriage House, located inside a closet. The handler will be replaced.



Chatham Laundry



View inside the basement of the Chatham Laundry



Air handler/chiller in the basement of the Chatham Laundry. The unit will be replaced.