



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

MW-3-01

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/23/2021
End Date: 2/23/2021

Well Logger: TRO
Date Installed: 2/23/2021

Easting (ft): 842844.551 **Horizontal Datum:** NAD83
Northing (ft): 1226027.693 **Vertical Datum:** NAVD88

Ground Elevation (ft): 27.8506
Reference Pt. Elevation (ft): 27.8506

Elev. (ft)	Depth (ft)	PID (ppm)	Well Construction Details	Lithologic Description	Notes
27	0		Steel Guard Pipe		
26	1				
25	2				
24	3		Grout		
23	4				
22	5				
21	6		Bentonite Seal		
20	7				
19	8			See boring log for SC-3-09.	Well located next to SC-3-09 Boring Location
18	9				
17	10				
16	11		Filter Sand		
15	12				
14	13				
13	14				
12	15				
11	16				

Drilling Company: OnSite Environmental
Drilling Method: Hollow Stem Augers
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: None

Borehole Depth (ft bgs): 16
Borehole Diameter (in.): 8
Well Diameter (in.): 1.5
Sampling Method: None

Filter Pack Interval (ft bgs): 7.5-16
Well Screen Interval (ft bgs): 9-14
Depth to Groundwater (ft bgs): dry

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-2-01

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/20/2021
End Date: 2/20/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 843569.995 **Horizontal Datum:** NAD83
Northing (ft): 1228150.778 **Vertical Datum:** NAVD88

Ground Elevation (ft): 20.1713
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
20	0			Black (2.5Y2.5/1), moist, stiff, gravelly SILT (ML)		
	1.3					
19.5	0.5					
	1.3		GRAVELLY SILT			
19	1					
	1.2					
18.5	1.5					
	0.0			Reddish Brown (2.5YR4/4), very stiff, silty CLAY (CL)		
18	2					
	0.0		SILTY CLAY			
17.5	2.5					
	0					
17	3			Pale Brown (2.5Y7/3), dry, loose, fine sandy SILT (ML)		
	0		SANDY SILT			
16.5	3.5					
	0					
16	4			No Recovery		
15.5	4.5		NR			
15	5			Light Gray (5Y7/2), dry, stiff, silty SAND (SW); little fine gravel		
	3.7					
14.5	5.5					
	0		SILTY SAND			
14	6					
	0.1					
13.5	6.5					
	3.7					
13	7					
	2.6					
12.5	7.5			Gray (5Y6/1), dry, medium stiff, fine sandy SILT (ML)		
	3.3					
12	8					
	1.0		SANDY SILT			
11.5	8.5					
	7.1					
11	9					
	5.4					
10.5	9.5					
	4.6					
10	10		NR	No Recovery		
	0.0		SANDY SILT	Gray (5Y6/1), dry, medium stiff, fine sandy SILT (ML) with fine gravel		
10						
10.5						

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 10.2
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-2-02

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/20/2021
End Date: 2/20/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 843582.052 **Horizontal Datum:** NAD83
Northing (ft): 1228004.554 **Vertical Datum:** NAVD88

Ground Elevation (ft): 16.729
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
0	2.6		SANDY SILT	Dark Brown/Black (5YR2.5/1), moist, sandy SILT (ML); little gravel		
16	0.8					
1	0.2		SILTY GRAVEL	Dark Gray (5YR4/1), dry/moist, silty GRAVEL (GM); fine to coarse gravel		
15	1.1					
2	0.5		SILT	Black (5YR2.5/1), very stiff, SILT (ML); little sand		
14	0.3					
3			NR	No Recovery		
13						
4						
12						
5	0		SILT	Black/Reddish Gray (5YR5/1), dry, SILT (ML); little gravel		
11			GRAVEL	Gray, dry, fractured GRAVEL (GM)		
6	1.3		SILT	Brown (7.5YR5/2), moist, very stiff, SILT (ML); little sand		
10	0.3		GRAVEL	Coarse GRAVEL (GM)		
7	0.5		SANDY CLAY	Reddish Brown (2.5YR4/4), moist, very stiff, sandy CLAY (CL)		
9	0.1		GRAVEL	Coarse GRAVEL (GM)		
8	0.4		GRAVELLY CLAY	Reddish Brown (2.5YR5/4), moist, very stiff, gravelly CLAY (CL)		
8	0.0		CLAY	Reddish Brown (2.5YR4/4), moist, very stiff, CLAY (CL); little fine-coarse gravel		
9	0.0					
7	0		NR	No Recovery		
10	0					
6	3.1		SANDY SILT	Light Gray (5Y7/2), moist, sandy SILT (ML); little gravel		
11	11.1					
5	0.7		SILTY GRAVEL	Light Gray (5Y7/1), dry, silty GRAVEL (GM)		
12	1.5					
4	0.0					
13						

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 12
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-2-03

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/20/2021
End Date: 2/20/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 843422.748 **Horizontal Datum:** NAD83
Northing (ft): 1227708.315 **Vertical Datum:** NAVD88

Ground Elevation (ft): 15.629
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
0	2.8			Dark Brown (10YR3/1), dry, dense, silty sandy GRAVEL (GM)		
15	2.4		SILTY GRAVEL			
1	1.3			Tan/Brown (2.5Y7/3), dry, dense, silty GRAVEL (GM)		
14	0.5		SILTY GRAVEL			
2	3.2					
13				No Recovery		
3			NR			
12						
4						
11						
5	45		SANDY SILT	Brown (7.5YR5/2), dry, sandy SILT (ML); little gravel		petroleum odor
10	51			Brown (7.5YR4/3), dry, dense, very stiff, sandy SILT (ML); little gravel		
6	87		SANDY SILT			
9	160					
7	39					
8	73		SILTY CLAY	Dark Gray (5Y4/1), moist, very stiff, silty CLAY (CL); little sand and gravel		
8	64					
8			NR	No Recovery		
7						
9	1.4		SILTY CLAY	Dark Gray (5Y4/1), moist, very stiff, silty CLAY (CL); little sand and gravel		
6	59					
10	21		SILTY GRAVEL	Dark Gray (5Y4/1), dry-moist, very stiff, silty/clayey GRAVEL (GM).		petroleum odor
5	91					
11	1		NR	No Recovery		Installed temporary 1" PVC Well - Dry
4	36		SILTY GRAVEL	Dark Gray (5Y4/1), dry-moist, very stiff, silty/clayey GRAVEL (GM).		
12	59		SILTY GRAVEL	Gray (5Y7/1), dry, silty GRAVEL (GM)		
3	60					
13			NR	No Recovery		
13	2.9		SILTY GRAVEL	Gray (5Y7/1), dry, silty GRAVEL (GM)		
2			Rock	Gray fractured Rock		
14						

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 13.2
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-2-04

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/20/2021
End Date: 2/20/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 843465.184 **Horizontal Datum:** NAD83
Northing (ft): 1227670.596 **Vertical Datum:** NAVD88

Ground Elevation (ft): 12.5557
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
12.55	0			Dark Gray (5Y4/1), moist, sandy SILT and GRAVEL (GM)		Step off 1' south - Refusal @ 1' on 2nd attempt
12.5	0.05					
12.45	0.1		GRAVEL			
12.4	0.15					
12.35	0.2			Gray Rock and Gravel with shells		
12.3	0.25		Rock			
12.25	0.3					
12.2	0.35					
12.15	0.4					
12.1	0.45					
12.05	0.5					
12	0.55					
11.95	0.6					
11.9	0.65					
11.85	0.7					
11.8	0.75					
11.75	0.8					
11.7	0.85					
11.65	0.9					
11.6	0.95					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 1
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-2-05

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/22/2021
End Date: 2/22/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 843420.545 **Horizontal Datum:** NAD83
Northing (ft): 1227720.279 **Vertical Datum:** NAVD88

Ground Elevation (ft): 15.6769
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
0	2.1		Asphalt	Black, moist, Asphalt and Gravel		
	14.7		GRAVEL	Gray, dry, GRAVEL (GM)		
	1.5		SANDY SILT	Black (7.5YR2.5/1), dry-moist, blocky sandy SILT (ML); little gravel		
14	0					
	1.8		GRAVELLY SILT	Pale Brown (10YR6/3), dry, stiff, gravelly SILT (ML); little sand		
	7.4					
	55					
12	42		SILTY CLAY	Gray (5Y5/1), moist, silty CLAY (CL); little sand		petroleum odor
	4		NR	No Recovery		
	5.1		SANDY SILT	Gray (5Y5/1), moist, stiff, sandy SILT (ML) with gravel		petroleum odor
10	35		SILT	Very Dark Gray (5YR3/1), moist, stiff, SILT (ML); little sand		
	25					
	20					
	7			Dark gray (5Y4/1), dry/moist, stiff, sandy SILT (ML) with gravel		
8	60		SANDY SILT			
	96					
	9.5					
6	46					
	4.2		NR	No Recovery		
10	10.4		SANDY SILT	Dark Gray (5Y4/1), moist, stiff, sandy SILT (ML); little gravel		
	75		GRAVELLY SILT	Gray (5Y6/1), dry, stiff, gravelly SILT (ML)		
	5					
4	5.5		SILTY CLAY	Very Dark Grayish Olive (10Y3/2), moist, very stiff, silty CLAY (CL); little sand		
	10					
	12.4					
	16		GRAVEL	Gray, dry, coarse GRAVEL (GM)		
2	2.9		SILTY CLAY	Very Dark Grayish Olive (10Y3/2), moist, very stiff, silty CLAY (CL); little sand and gravel		
	12.5					
	5.4		NR	No Recovery		
	4		SILTY CLAY	Very Dark Grayish Olive (10Y3/2), moist, very stiff, silty CLAY (CL); little sand and gravel		
0	5.7					
	6					
	7.4					
	1.3		GRAVEL	Gray, dry, GRAVEL (GM)		
2	3.2		SILTY SAND	Olive Gray (5Y5/2), moist, stiff, silty SAND (SW)		
	9.4					
	21					
	11.6		SANDY CLAY	Olive Gray (5Y5/2), silty sandy CLAY (CL)		
4	18.4		NR	No Recovery		
	5.6		SILTY SAND	Gray (2.5Y5/1), moist, very stiff, silty SAND (SW); little gravel		slight petroleum odor
	9.0					
	5.0		SANDY SILT	Very Dark Gray (2.5Y3/1), sandy SILT (ML)		
6	9.3		GRAVELLY SILT	Light Brownish Gray, stiff, fine gravelly SILT (ML)		
	15.5		SILTY SAND	Gray (5Y5/1), dry, silty SAND (SW)		
8	24					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 23
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-01

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/17/2021
End Date: 2/17/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842983.247 **Horizontal Datum:** NAD83
Northing (ft): 1226005.399 **Vertical Datum:** NAVD88

Ground Elevation (ft): 20.3582
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
20	0	0.9	SANDY SILT	Brown, moist, sandy SILT (ML); trace gravel and glass fragments		
19	1		NR	No Recovery		
18	2					
17	3					
16	4					
15	5	1.3	SANDY SILT	Dark Brown, moist, sandy SILT (ML); trace gravel and wood fragments		
14	6	1.6	Concrete	Concrete		
			SANDY GRAVEL	Brown, moist, sandy GRAVEL (GM)		
			Concrete	Concrete		
			SANDY SILT	Brown, moist, sandy SILT (ML); trace gravel		
			Wood	Brown, moist, wood fragments (tree)		
13	7	3.6	GRAVEL	White, dry, GRAVEL (Old Concrete)		
		3.9	SANDY SILT	White/Brown, dense sandy SILT (ML); concrete fragments		
12	8	5.3		No Recovery		
11	9		NR			
10	10		SANDY SILT	Brown, moist, sandy SILT (ML); little coarse gravel		
9	11		Rock	White, fractured ROCK		
8	12			No Recovery		
7	13		NR			
6	14					
15	15					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: None

Borehole Depth (ft bgs): 15
Borehole Diameter (in.): 2.5
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-02

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/19/2021
End Date: 2/19/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842921.854 **Horizontal Datum:** NAD83
Northing (ft): 1226034.524 **Vertical Datum:** NAVD88

Ground Elevation (ft): 27.2802
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
27	0		Grass	Grass		PID malfunction due to high humidity
			Concrete	Concrete		
			GRAVELLY SILT	Brown, moist, gravelly SILT (ML); some sand		
26	1		Leaves/sticks	Brown, moist, leaves/sticks/plastic		
				No Recovery		
25	2		NR			
24	3		SANDY SILT	Brown, moist, sandy SILT (ML)		
			Wood	Brown, moist, wood and leaf litter		
			GRAVEL	Greenish Gray GRAVEL (GM)		
23	4		GRAVELLY CLAY	Dark Gray, moist, sandy gravelly CLAY (CL)		
				No Recovery		
22	5		NR			
21	6		GRAVELLY CLAY	Dark Gray, moist, sandy gravelly CLAY (CL)		
			Leaf litter	Dark Brown, moist, leaf litter		
			SANDY SILT	Brown, moist, sandy SILT (ML) and leaf litter		
			Leaf litter	Dark Brown, moist, woody leaf litter		
20	7		Concrete	White/Gray Concrete		
			GRAVELLY CLAY	Greenish Gray, moist, gravelly CLAY (CL)		
19	8		GRAVELLY SILT	Dark Brown, moist, gravelly SILT (ML); trace plastic fragments		
18	9		SAND	Tan, moist, SAND (SW)		
			SILT	Dark Brown, moist, SILT (ML) with organics		
			NR	No Recovery		
17	10		SILTY CLAY	Dark Brown, moist, silty CLAY (CL)		
			SILT	Dark Brown, moist, SILT (ML) and organics		
			SANDY SILT	Gray, dry, sandy SILT (ML); little gravel		
16	11		GRAVELLY SILT	Dark Gray, moist, sandy gravelly SILT (ML); trace organics		
15	12		SANDY SILT	Dark Brown, moist, sandy SILT (ML) and woody material		
14	13		NR	No Recovery		
13	14		NR			
12	15		SILT	Dark Brown, moist, firm SILT (ML) with woody material		
			SANDY GRAVEL	Brown, moist, sandy GRAVEL (GM)		
			SANDY GRAVEL	Gray, moist, dense, silty sandy GRAVEL (GM)		
11	16		SANDY SILT	Dark Brown, moist, dense sandy SILT (ML)		
10	17		SILTY SAND	Greenish Gray, moist, firm, silty SAND (SM); little gravel		
18	18		NR	No Recovery		

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 18
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-03

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/19/2021
End Date: 2/19/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842870.548 **Horizontal Datum:** NAD83
Northing (ft): 1226060.828 **Vertical Datum:** NAVD88

Ground Elevation (ft): 25.7475
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
0	13.8		SANDY SILT	Brown, dry, sandy SILT (ML)		
			Wood	Brown, dry, woody material		
25	18		Concrete	Gray/White Concrete		
1	7.3		SANDY SILT	Brown/Tan, dry, sandy SILT (ML); little gravel		
24	9.0			No Recovery		
2			NR			
3	0.3		SANDY SILT	Brown, dry, sandy SILT (ML); some gravel		
22	18.1		SILTY GRAVEL	Brown, dry, silty GRAVEL (GM)		
4	1.5		GRAVELLY SILT	Brown/Dark Brown, moist, gravelly SILT (ML)		
			SILTY CLAY	Dark Brown, moist, silty CLAY (CL); trace gravel		
21			NR	No Recovery		
6			SANDY SILT	Brown, dry, sandy SILT (ML); trace gravel		
19	0		GRAVELLY SILT	Dark Brown, moist, gravelly SILT (ML); trace woody material		
18			SAND	Tan, moist, SAND (SW)		
				Dark Brown, moist, sandy SILT (ML); trace woody material		
8	0.5		SANDY SILT			
17	0		SILTY GRAVEL	Brown/Gray, moist, dense, sandy silty GRAVEL (GM); trace plastic		
16			NR	No Recovery		
15			SILT	Dark Brown, moist, SILT (ML); little sand and peat		
11			Concrete	Gray, dry, Concrete		
14			GRAVELLY SAND	Greenish Gray, moist, dense, gravelly SAND (GM)		
13				Gray, dense, gravelly SILT (ML)		
12			GRAVELLY SILT			
11			NR	No Recovery		

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 15
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-04

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/19/2021
End Date: 2/19/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842868.302 **Horizontal Datum:** NAD83
Northing (ft): 1225975.983 **Vertical Datum:** NAVD88

Ground Elevation (ft): 27.799
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
0	0		GRAVEL	Brown, dry, GRAVEL (GM)		
			SANDY GRAVEL	Brown, dry, silty sandy GRAVEL (GM)	SC-3-04(0.5)	waste characterization
26	2		Leaf litter	Dark Brown, moist, leaf litter		
			SANDY SILT	Dark Brown, moist, sandy SILT (ML); little gravel; trace leaf litter	SC-3-04(0-3)	
			NR	No Recovery		
	0		SILTY GRAVEL	Brown, dry, silty GRAVEL (GM)		
24	1.2		SAND	Tan/Dark Brown, leaf litter and SAND (SW); trace woody material		
	0.3		Wood		SC-3-04(3-6)	
			Concrete			
			NR	Brown, moist, woody material		
				Gray, moist, old concrete; trace leaf litter		
				No Recovery		
22	6		Leaf litter	Brown, moist, leaf litter and sand/silt		
			GRAVEL	Gray, moist, GRAVEL (GM); little leaf litter		
	2.8		GRAVELLY SILT	Gray/Tan, moist, gravelly sandy SILT (ML)		
20	8		SAND	Gray/Tan, moist, SAND (SW); little silt and gravel		
			NR	No Recovery		
18	10		SAND	Gray/Tan, moist, SAND (SW); little silt and gravel		
	22		SILT	Gray, moist, dense, SILT (ML) with sand and wood fragments		
	44		SANDY SILT	Dark gray, moist, sandy SILT (ML); trace gravel		
	12.2		SAND	White, moist, SAND (SW)		
16	4.5		SANDY SILT	Gray, moist, firm, sandy SILT (ML)		
	2.7		SANDY GRAVEL	Gray, moist, sandy GRAVEL (GM)		
	12.2		SANDY SILT	Dark Brown, moist, sandy SILT (ML) with woody material and plastic (fill)		
			NR	No Recovery		
14	14					
	5.9		GRAVEL	White GRAVEL (GM); little dark brown silt		
	17		SANDY SILT	Dark Brown, moist, sandy SILT (ML)		
12	11.6		SANDY SILT	Dark Brown, moist, sandy SILT (ML) with woody material and plastic (fill)		
	7.8		Concrete			
	8.5		SANDY CLAY	Brown, moist, silty SAND (SW)		
	11.5		SANDY SILT	Gray/White Concrete		
10	18			Black, moist, sandy CLAY (CL); 1/2" ribbon		
			NR	Dark Brown, moist, sandy gravelly SILT (ML) with plastic and wood		
				No Recovery		
8	20					
	0		SANDY SILT	Dark Brown, moist, sandy gravelly SILT (ML) with plastic and wood		
	2.6					
	9					
6	8.7		GRAVEL	Gray/White, dry, GRAVEL (GM)		
	2.0			Greenish Gray, moist, dense, sandy silty GRAVEL (GM)		
	4.6					
	2.7		SILTY GRAVEL			
4	9.6					
	1.3					
	0		NR	No Recovery		
2	0		SANDY SILT	Dark Brown, moist, sandy SILT (ML) with gravel, plastic and wood (spoil)		
	1.5		SILTY GRAVEL	Greenish Gray, stiff, silty sandy GRAVEL (GM)		
	0.4					
	0.7		Rock	White/Gray fractured ROCK		
	0.8					
0	28					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 27
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-05

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/19/2021
End Date: 2/19/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842991.288 **Horizontal Datum:** NAD83
Northing (ft): 1226086.59 **Vertical Datum:** NAVD88

Ground Elevation (ft): 29.142
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
29.1	0			Refusal on Rock		Refusal between 0 and 1.5 feet at 3 locations
	0.1					
29	0.2					
	0.3					
28.9	0.4					
	0.5					
28.8	0.6					
	0.7					
28.7	0.8					
	0.9					
28.6	1					
	1.1					
28.5	1.2					
	1.3					
28.4	1.4					
			Rock			
28.3						
28.2						
28.1						
28						
27.9						
27.8						
27.7						

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 1.5
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-06

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/19/2021
End Date: 2/19/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842954.787 **Horizontal Datum:** NAD83
Northing (ft): 1226070.411 **Vertical Datum:** NAVD88

Ground Elevation (ft): 27.2519
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
27	0	0.0	SILTY GRAVEL	Brown, moist, silty GRAVEL (GM) with grass		1st attempt refusal @2.0', move 4' southwest
	0.5		SANDY GRAVEL	Tan/Brown, dry, dense, silty sandy GRAVEL (GM)		
26	1	0.9	SILTY GRAVEL	Dark Brown, moist, silty GRAVEL (GM) with organics		
	9.7		SANDY GRAVEL	Dark Brown, moist, silty sandy GRAVEL (GM) with woody material and waste (paper/foil)	SC-3-06(0-3)	
			CLAY	Gray, moist, CLAY (CL) - sludge?		
25	2		SILT	Dark Brown, moist, sandy SILT (ML) with foil waste		
			NR	No Recovery		
24	3	0	SANDY SILT	Brown, dry, sandy SILT (ML) with woody material and plastic		
	0.2		GRAVELLY SILT	Dark Brown, moist, gravelly SILT (ML) with coral fragments		
	1.3		SANDY SILT	Black, moist, sandy SILT (ML)		
23	6.0		SANDY SILT			
	6.8		SILTY SAND	Greenish Gray, moist, silty SAND (SW); some gravel	SC-3-06(3-6)	
22			NR	No Recovery		
21	6	0	SANDY SILT	Brown, dry, sandy SILT (ML); some gravel and woody material	SC-3-06(0-6) waste characterization	
			Coral	fractured coral		
20	0		SAND	Greenish Gray, moist, dense, SAND (SW); little gravel; trace silt		
19	0		SAND			
			SILTY CLAY	Dark Gray, moist, silty CLAY (CL)		
18	0		SAND	Greenish Gray/Brown, dry, SAND (SW); little gravel		
			SAND			
17	0		GRAVELLY SILT	Brown, dry, dense, gravelly SILT (ML)		
16	0		GRAVELLY SILT			
			SANDY SILT	Tan, dry, dense, sandy SILT (ML)		
15	0		SANDY SILT			
14	0		SANDY SILT			
13	0		SANDY SILT			
			NR	No Recovery		
15			NR	No Recovery		

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 15
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-07

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/19/2021
End Date: 2/19/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 843008.132 **Horizontal Datum:** NAD83
Northing (ft): 1226036.733 **Vertical Datum:** NAVD88

Ground Elevation (ft): 23.8267
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
23.6	0			Brown, moist, sandy SILT (ML)		
23.2	0.4	3.6	SANDY SILT			
22.8	0.8	2.4	SILTY GRAVEL	Gray, moist, silty GRAVEL (GM)		
22.4	1.2		Wood	Brown, dry, woody material		
22.0	1.6		SILT	Dark Brown, moist, SILT (ML)	SC-3-07(0-3)	
21.6	2.0	3.6	SANDY SILT	Brown, moist, dense sandy SILT (ML)		
21.2	2.4			No Recovery		
20.8	2.8		NR			
20.4	3.2					
20.0	3.6	0	SANDY GRAVEL	Brown, dry, sandy GRAVEL (GM)		
19.6	4.0		SILT	Greenish Gray, stiff, SILT (ML)		
19.2	4.4			Tan/Brown, dry, dense, silty SAND (SW)	SC-3-07(3-6)	
18.8	4.8	0.2	SILTY SAND			
18.4	5.2					
18.0	5.6	0			SC-3-07(2-6) waste characterization	
17.6	6.0					
17.2	6.4	0	SANDY GRAVEL	Brown, dry, sandy GRAVEL (GM)		
16.8	6.8			Greenish Gray/Brown, dry, silty SAND (SW); little gravel		
16.4	7.2		SILTY SAND			
16.0	7.6	0				

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 8
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-08

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/21/2021
End Date: 2/21/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842883.206 **Horizontal Datum:** NAD83
Northing (ft): 1226108.436 **Vertical Datum:** NAVD88

Ground Elevation (ft): 25.3042
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
25	0	11.6	SANDY SILT	Dark Gray (7.5YR4/1), dry, sandy SILT (ML); little waste/foil		fill from 0 - 12 feet
	6.6					
	7.5		SILTY SAND	Light Gray (7.5YR5/1), dry, silty SAND (SW)		
24	1	6.5	SANDY SILT	Black (7.5YR2.5/1), moist, sandy SILT (ML) with concrete gravel	SC-3-08(0-3)	
	4.2					
	3.1			No Recovery		
23	2					
	3		NR			
22						
	4				SC-3-08(3-6)	
21						
20	5	3.3	GRAVELLY SILT	Gray (7.5YR5/1), dry, gravelly SILT (ML); little sand	SC-3-08(0-5)	waste characterization
	0.4					
19	6	1.1	SILT	Black (7.5YR2.5/1), moist, stiff, SILT (ML); little sand		
	1.2					
18	7	0.3		Light Gray (5Y7/1), dry, silty rotted Rock		
	0.9		Rock			
17	8	3.3				
	1.0		GRAVELLY CLAY	Light Reddish Brown (2.5YR3/4), moist, very stiff, gravelly CLAY (CL)		
16	9	3.3				
	7.8					
			NR	No Recovery		
15	10	11.2	GRAVELLY CLAY	Light Reddish Brown (2.5YR3/4), moist, very stiff, gravelly CLAY (CL)		
	1.9		SANDY SILT	Dark Gray (2.5YR4/1), dry, sandy SILT (ML) with gravel; brick, glass, and tar paper waste		
14	11	0.9	SILTY SAND	Dark Gray (7.5YR4/1), dry, silty SAND (SW); little fine gravel and concrete/glass shards		
	2.7			Light Gray (2.5Y7/1) grading to 2.5Y6/2), silty SAND (SW); little gravel		
13	12	10.2				
	3.1		SILTY SAND			
13	13	5.5				
	6.2					
14	14	6.4				
11			NR	No Recovery		
15	15					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 15
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-09

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/21/2021
End Date: 2/21/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842844.293 **Horizontal Datum:** NAD83
Northing (ft): 1226027.501 **Vertical Datum:** NAVD88

Ground Elevation (ft): 25.0775
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
25	0	1.6	SANDY SILT	Dark Gray (7.5YR4/1), dry, sandy SILT (ML); little gravel and wood/roots/grass		No Waste Characterization Sample Collected
24	1	0	SANDY SILT	Dark Gray (7.5YR4/1), dry, sandy SILT (ML); little gravel and wood/carpet backing material	SC-3-09(0-3)	
23	2		NR	No Recovery		
22	3	0	SANDY SILT	Gray (7.5YR5/1), dry, sandy SILT (ML) with wood fragments		
		0.3	SANDY SILT	Dark Gray (7.5YR3/1), dry/moist, sandy SILT; some coarse gravel		
21	4	1.6	GRAVELLY SAND	Pale Yellow (5Y7/4), moist, gravelly SAND (SW) with woody material		
		1.0	SAND	Light Gray (10YR7/2), fine SAND (SW)	SC-3-09(3-6)	
20	5		NR	No Recovery		
19	6	0	SANDY SILT	Grayish Brown (2.5Y5/2), dry, sandy SILT (ML); little gravel with plastic, shells, carpet fibers		
18	7	0	SANDY SILT	Black (2.5Y2.5/1), moist, sandy SILT (ML); trace gravel with woody material		
17	8	0	SILTY SAND	Gray (2.5Y5/1), moist, silty SAND (SW); little gravel		
16	9		NR	No Recovery		
15	10	0	SILTY SAND	Gray (2.5Y5/1), moist, silty SAND (SW); little gravel		
14	11	0		Dark Grayish Brown (2.5Y4/2), moist, stiff, gravelly SILT (ML); some sand		
13	12	0	GRAVELLY SILT			
12	13	0				
11	14	0	SANDY GRAVEL	Light Gray (2.5Y7/2), dry, very stiff, sandy GRAVEL (GM)		
10	15		NR	No Recovery		
9	16	0	GRAVELLY SILT	Very Dark Gray (2.5Y3/1), moist, gravelly SILT (ML); little sand		
		0				
8	17	0	SILTY SAND	Brownish Gray (2.5Y6/2), moist, silty SAND (SW); some gravel		
7	18	0	GRAVELLY SAND	Light Brown (7.5YR6/4), dry, stiff, gravelly SAND (SW)		
			Rock	Gray, dry, Rock fragments		

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 19
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1

SC-3-10

Well Logger: N/A
Date Installed: N/A

Ground Elevation (ft): 26.4382
Reference Pt. Elevation (ft): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-3-11

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/21/2021
End Date: 2/21/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842928.297 **Horizontal Datum:** NAD83
Northing (ft): 1225997.234 **Vertical Datum:** NAVD88

Ground Elevation (ft): 24.9893
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
25	0	0	GRAVELLY SILT	Grayish Brown (2.5Y5/3), dry, gravelly SILT (ML) with grass and roots		
		0	SILTY GRAVEL	Gray (2.5Y5/1), dry, silty GRAVEL (GM)		
24	1	0	Fill	Dark Gray (10YR4/1), dry, silty woody material with plastic (Fill)		
		0	GRAVEL	GRAVEL (GM)		
		0	Wood	Wood fibers		
		0	SILT	Dark Gray (10YR3/1), moist, stiff, SILT (ML)	SC-3-11(0-3)	
23	2		NR	No Recovery		
22	3	0	GRAVELLY SILT	Dark Gray (2.5Y4/1), dry, gravelly SILT (ML)		
		0	SANDY SILT	Black (2.5Y2.5/1), moist, stiff, sandy SILT (ML)		
21	4		Fill	Woody material and plastic	SC-3-11(3-6)	
			NR	No Recovery		
20	5		NR		SC-3-11(0-5) waste characterization	
19	6	0	SANDY SILT	Brown (7.5YR4/2), dry, loose, sandy SILT (ML); little gravel		
18	7	25.1	SANDY SILT	Dark Gray/Light Green (7.5YR3/1), moist, sandy SILT (ML) with woody material and plastic		
		26.5	SANDY SILT			
17	8	1.0	GRAVELLY SILT	Olive Gray (5Y6/2), moist, gravelly SILT (ML)		
		1.1	SANDY SILT	Very Dark Gray (10YR3/1), moist, sandy SILT (ML)		
16	9		NR	No Recovery		
15	10	0.0	SANDY SILT	Very Dark Gray (10YR3/1), moist, sandy SILT (ML)		
14	11	2.1	GRAVELLY SILT	Grayish Brown (10YR5/2), sandy gravelly SILT (ML) with concrete fragments (Fill)		
		0.0	GRAVELLY SILT			
13	12		NR	No Recovery		

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 12
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-Ref-01

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/21/2021
End Date: 2/21/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842928.349 **Horizontal Datum:** NAD83
Northing (ft): 1226179.317 **Vertical Datum:** NAVD88

Ground Elevation (ft): 44.7809
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
44.76	0			Light Brown (7.5YR6/3), dry, sandy SILT (ML); little gravel		
44.72	0.04					
44.68	0.08					
44.64	0.12					
44.6	0.16					
44.56	0.2	0.2	SANDY SILT			
44.52	0.24					
44.48	0.28					
44.44	0.32					
44.4	0.36					
44.36	0.4					
44.32	0.44					
44.28	0.48					
44.24	0.52			Gray, dry, Rock/Gravel	SC-Ref-01(0-0.5)	
44.2	0.56					
44.16	0.6	3.8	Rock			
44.12	0.64					
44.08	0.68					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 0.7
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-Ref-02

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/21/2021
End Date: 2/21/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842869.392 **Horizontal Datum:** NAD83
Northing (ft): 1226296.391 **Vertical Datum:** NAVD88

Ground Elevation (ft): 44.9843
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
44.8	0		SANDY SILT	Dark Gray (7.5YR4/1), dry/moist, sandy SILT (ML) with roots		
44.6	0.1			Pale Brown (2.5Y7/3), dry, silty SAND (SW); little gravel		
44.4	0.4					
44.2	0.6	0				
44	0.8		SILTY SAND			
43.8	1					
43.6	1.2					
43.4	1.4					
43.2	1.6	0	GRAVEL	Pale Brown (2.5Y7/3), GRAVEL (GM); little silt	SC-Ref-02(0-2.6)	
43	1.8			Light Gray (2.5Y7/1), dry, sandy SILT (ML); some gravel		
42.8	2		SANDY SILT			
42.6	2.2	5.1				
42.4	2.4					
42.4	2.6					

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 2.6
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1



Vanasse Hangen Brustlin, Inc.
100 State St. Suite 600
Montpelier, VT 05602
(802) 229-4600

SC-Ref-03

Project: Caneel Bay Resort Site
Location: St. John, U.S. Virgin Islands
Project Number: 58345.21

Soil Logger: TRO
Start Date: 2/21/2021
End Date: 2/21/2021

Well Logger: N/A
Date Installed: N/A

Easting (ft): 842808.402 **Horizontal Datum:** NAD83
Northing (ft): 1226199.962 **Vertical Datum:** NAVD88

Ground Elevation (ft): 46.3301
Reference Pt. Elevation (ft): --

Elev. (ft)	Depth (ft)	PID (ppm)	Lithology	Lithologic Description	Sample ID	Notes
46.2	0	0	SANDY SILT	Dark Gray (2.5Y4/1), dry, sandy SILT (ML); little fine-coarse gravel and glass fragments		
46	0.2					
45.8	0.4					
45.6	0.6	0				
45.4	0.8					
45.2	1					
45	1.2					
44.8	1.4	0				
44.6	1.6				SC-Ref-03(0-3)	
44.4	1.8			No Recovery		
44.2	2		NR			
44	2.2					
43.8	2.4					
43.6	2.6					
43.4	2.8					
43.2	3					
43	3.2	0.0	SANDY SILT	Dark Gray (2.5Y4/1), dry, sandy SILT (ML); little concrete/gravel		
42.8	3.4					
42.6	3.6	2.7	Rock	Dark Gray Rock Fragments		

Drilling Company: OnSite Environmental
Drilling Method: Direct Push Technology (DPT)
Drilling Rig: Geoprobe 6620DT
Drilling Fluid: --

Borehole Depth (ft bgs): 4
Borehole Diameter (in.): 3
Well Diameter (in.): N/A
Sampling Method: Macrocore Dual Tube

Filter Pack Interval (ft bgs): N/A
Well Screen Interval (ft bgs): N/A
Depth to Groundwater (ft bgs): --

Drawn by: TEH
Revision: 0
Page 1 of 1